Feature Summary

Hollander Interchange Version 88.01



Updated Part Coverage

The **88.01** Interchange release provides coverage for **90 new models**. (1-2019, 10-2020, 41-2021, 38-2022)

BMW

- M340i (Sdn) 2020
- i3 2020
- X3 2021
- X5 2021
- X5M 2021

Chevrolet

- Equinox 2021
- Silverado 1500 2021
- Silverado 2500 2021
- Silverado 3500 2021
- Tahoe 2022
- Traverse 2021

Ford

- Bronco Sport 2022
- Explorer 2021-2022
- F150 2022
- F250SD 2021-2022

GMC

- Sierra 1500 2021
- Sierra 2500 2021
- Sierra 3500 2021
- Sierra Denali 1500 2021
- Sierra Denali 2500 2021
- Sierra Denali 3500 2020-2021

Honda

- Accord 2022
- Clarity fuel cell 2021
- HR-V 2022
- Insight 2022
- Passport 2022
- Pilot 2022

Hyundai

- Kona 2021
- Palisade 2021-2022
- Sonata 2022
- Tucson 2021-2022

Jeep

- Cherokee 2022
- Compass 2022
- Gladiator 2021
- Grand Cherokee 2022
- Wrangler 2021

KIA

- Forte 2021
- Seltos 2022
- Telluride 2021-2022

Lexus

- RX350 2020-2022
- RX350L 2020-2022
- RX450h 2020-2022
- RX450hL 2020-2022

Mazda

- CX-3 2019
- CX-5 2022
- 6 2020

Nissan

- Altima 2021-2022
- Frontier 2021-2022
- Pathfinder 2022
- Rogue 2022
- Sentra 2021-2022

RAM

- 1500 2021
- 2500 2021-2022

Subaru

- Crosstrek 2022
- Forester 2022
- Outback/Legacy 2022

Toyota

- 4Runner 2021-2022
- Camry 2021
- Corolla 2021-2022
- Highlander 2022
- Rav4 2021
- Sienna 2022
- Tacoma 2021-2022
- Tundra 2021

Volkswagen

- Atlas 2020-2021
- Atlas Cross Sport 2020-2022

New Reference Part Types

The following Part Types have been added to the Hollander Interchange:

PartType	Description	PartType	Description
142	Door Shell, Fr	286	Door Latch, Rr
143	Door Shell, Rr	287	Door Latch, Bk
144	Door Shell, Bk	665	Tailgate Lift Motor
285	Door Latch, Fr		

Feature Summary

Hollander Interchange Version 88.01



Added Interchange Coverage

Partial interchange data is now available for Key Fobs (Part Type 654). Interchange numbers were added for key fobs that were determined to have resale value. Most fobs made before 2005 have little or no value with the bulk of fobs that have value appearing in 2010 and later vehicles. The Hollander Interchange v88.01 release includes roughly 580 interchange numbers for Key Fobs with over 1400 applications.

New Images

In this Interchange release (v88.01), 679 Wheel (Part Type 560) and 9 Wheel Cover (Part Type 570) images were added.

Interchange Action Request (IARs)

Our policy at Hollander is to write the Interchange to reflect the wishes of our clients. Our client contacts (road and trade shows, regional and association meetings, and feedback to our support and Interchange departments), provide us with guidance on the Interchange. The latest input from all Interchange users is incorporated into this Interchange release. We processed 442 Interchange Action Requests (IARs); 348 data changes were implemented, and 81 Notes and Idents were added.

Submitting IARs

Our policy at Hollander is to write the Interchange to reflect the wishes of our clients. IARs can be submitted via email, the online form, or through the Powerlink Yard Management System.

Submit an IAR through Email or Online Form

■ Email: <u>interchange@hollanderparts.com</u>

When submitting an email request, include the following information:

Part Type
Interchange #

Manufacturer
Hollander Interchange Release

Year
Model

VIN (if applicable)
Description of Request

Online: <u>my.hollandersolutions.com/contact-us</u>

Visit my.hollandersolutions.com/contact-us and then log in*. Select Interchange Action Request from the Type of Request drop-down menu. Complete the online form and click the Submit button.

*Please note: You must be a registered Hollander Training Portal user to submit an IAR online. You can create an account by clicking Login and then clicking Create Account.

Submit an IAR through Powerlink

Click the Tools menu and select Send SARs and IARs. Complete the form and then click Submit.

